HUMOR 20 + Automatic Calibration Module



HUMIDITY CALIBRATOR

MANUAL Hardware + Software



TABLE OF CONTENTS

1	FOREWORD	3
2	EC DECLARATION OF CONFORMITY	4
3	SCOPE OF SUPPLY 3.1 HUMOR 20 3.2 Automatic calibration module (optional)	4 4 5
4	SAFETY INSTRUCTIONS 4.1 General 4.2 HUMOR 20	5 5 5
5	OPERATING PRINCIPLE	6
6	OPERATING COMPONENTS 6.1 HUMOR 20 6.2 Automatic calibration module (optional)	7 7 7
7	GENERAL USER INSTRUCTIONS 7.1 Setup 7.2 Starting up HUMOR 20 7.3 Starting up HUMOR 20 with automatic calibration module 7.4 Verifying the 100 %RH Point	7 7 8 9 11
8	CALIBRATION AND ADJUSTMENT PROCEDURE 8.1 Cubical transmitters (room design) with HUMOR 20 8.2 Transmitter with cylindrical sensor probe with HUMOR 20 8.3 Transmitter EE33 Model J with HUMOR 20 8.4 Analogue output HUMOR 20 8.5 Calibrations with the automatic calibration module 8.6 Power failure during the calibration procedure 8.7 Ending the calibration or adjustment procedure	12 13 13 14 14 14 14
9	HUMOR 20 SOFTWARE 9.1 Installing the software 9.2 Configuration mode control panel 9.3 Menu bar 9.3.1 Operation 9.3.2 Calibration 9.3.3 Pressure Compensation 9.4 Measurements 9.4.1 Start screen 9.4.2 "Test unit" configuration field 9.4.3 "Measurements" configuration field 9.5 Fixed RH Value	15 16 16 22 25 26 26 26 28 29
10	MAINTENANCE 10.1 Re-fill water (at error message Water-Level low) 10.2 Drain water (at error message Water-Level high or long idle periods)	29 29 29
11	WARNINGS / ERROR MESSAGES IN THE DISPLAY 11.1 Humidity - display flashes 11.2 Warning: OUT OF SPEC 11.3 Warning: WATERLEVEL HIGH 11.4 Warning: WATERLEVEL LOW 11.5 Error message: heat defect 11.6 Error message: pressure excess 11.7 Humidity - indication is not correct 11.8 Stabilisation time too long 11.9 Electronic defect - replace electronics 11.10 Leakage in filter set	30 31 31 31 31 31 31 32 32 32
12	TECHNICAL DATA	33

LIMITED LIABILITY

E+E Elektronik[®] shall not be held liable for any damage or consequential damage (for example, but not restricted to, loss of earnings, interruption of business, loss of information and data or any other financial losses) resulting from the setup, use or impossibility of use of an E+E Elektronik[®] software product and any associated support services or non-performance of support services.

E+E Elektronik® Ges.m.b.H. is not responsible for the completeness of this publication and shall not be liable for the products described herein in the event of improper handling.

This publication may contain technical inaccuracies or typographical errors. The information contained herein is revised regularly. These changes will be implemented in later editions. The products described herein may be improved or changed at any time.

© Copyright E+E Elektronik GmbH // All rights reserved // Subject to change without notice

1 FOREWORD

E+E Elektronik[®] Ges.m.b.H. developed this device to accurately generate the relative humidity (Uw).

As such, this professional tool represents the manufacturer's current status of knowledge with regard to development, design and production. The manufacturer is confident that the humidity calibrator HUMOR 20 meets all the requirements and expectations that you, the buyer, demand of a new acquisition. If the device is handled properly and serviced regularly it should work reliably for several years.

This manual forms part of the scope of supply and serves to ensure proper handling and optimal performance of the device.

Therefore, make sure you read the manual before you take the device into operation. The manual is also to be brought to the attention of any person involved in transport, setup, operation, maintenance or repair.

This manual must not be used for competitive purposes without our written consent and must not be passed on to third parties. Copies for personal use are permitted.

All information, technical data and illustrations contained in this manual are based on the information available at the time of publication.

E+E Elektronik[®] Ges.m.b.H. reserves the right to change the technical data or make other technical modifications at any time and without prior notice without being committed to retrofitting models produced before such a change was made.

General

This manual is part of the scope of supply and serves to ensure the optimum operation and performance of the device.

To ensure correct operation, this manual must be read before the device is taken into operation.

Explanation of symbols



This symbol indicates a safety instruction.

These safety instructions must always be followed. The manufacturer is not liable for any damage resulting from non-compliance. In this case, the user is solely responsible for his actions.



This symbol indicates a note.

These notes should be observed to achieve optimal performance of the equipment.

2 EC DECLARATION OF CONFORMITY

The manufacturer declares that the device mentioned hereinafter complies wiht the pertinent EC Directives relating to safety and health requirements with regard to its design, construction and current version. If unauthorised alterations are made to the device, this declaration is no longer valid.

Manufacturer

E+E Elektronik® GmbH Langwiesen 7, A-4209 Engerwitzdorf Tel.: +43 7235 605-0 // Fax: +43 7235 605-8 info@epluse.com // www.epluse.com

Designation of the device: HUMOR 20

HUMOR 20 is a professional instrument generating relative humidity, used to check (calibrate, adjust) humidity measuring devices.

The device complies with the

EC Electromagnetic Compatibility Directive (2004/108/EC) EC Low Voltage Directive (2006/95/EC)

Harmonised standards	
EN 61000-6-4	EN 60068-2-6
EN 61000-6-2	EN 61010-1
EN 61326-1	EN61326-2-3
EN 60068-2-29	

3 SCOPE OF SUPPLY



1 Power supply cable IEC Europe (230V) + power supply cable IEC Northamerica (110V)

- Water drain pipe with connector 2
- 3 Funnel
- Allen key (10mm / 0.4") 4
- Measuring beaker 5
- Measuring and calibration software 6

Filter set with oil separator

- Plexiglas cover for room transmitter testing
- 9 O-ring for plexiglas cover
 - Knurled nut

Cover for measuring chamber, ordering code HA0202xx (not inlcuded in the scope of supply)

- 12 Bracket for separator / filter set (pre-mounted)
- 13 Works certificate acc. DIN EN 10204-3.1 14
 - RS232 cable for PC

8

10

11

3.2 Automatic calibration module (optional)



- Automatic calibration module
- Power supply cable IEC Europe (230V)
- Power supply cable IEC North America (110V)
- RS232 connection cable to HUMOR 20
- Compressed-air connecting hose to HUMOR 20

4 SAFETY INSTRUCTIONS

4.1 General

HUMOR 20 is designed based on state-of-the-art technology, which means it will operate reliably if it is kept in good condition and operated and serviced correctly. This device may pose a risk if it is operated improperly by untrained personnel.

Improper use can: • Injure operating personnel and damage the device itself or other assets belonging to the user.

Prevent the device from working efficiently and accurately.

Observe the following information to ensure operational safety:



- Only qualified or specially trained staff may operate or perform work on the humidity calibrator. Unauthorised changes or modifications are either not permitted or require the express permission of the manufacturer.
- Read this manual carefully before taking the device into operation. The manual must also be made available to any person involved in transport, setup, operation, maintenance or repair (particularly when loaning or selling the device to a third party).
- Only operate the device if it is in good condition. Any fault must be repaired by authorised personnel or by an E+E Elektronik sales partner before it is taken into operation again.

4.2 HUMOR 20

- Check whether the supply voltage data on the nameplate matches the local supply voltage.
- Only power the humidity calibrator via a grounded power outlet (safety precaution).
- Before opening the water intake, make sure that the humidity calibrator is no longer under pressure (controller turned to the left as far as it will go; if HUMOR 20 already in service, display shows RH > 90%).
- HUMOR 20 may only be operated with distilled (deionised) water.
- Before connecting the compressed air or nitrogen supply, make sure that the controller is turned to the left as far as it will go.
- The device may only be operated with filtered compressed air with a contamination level of <0.01mg/m³.
- The media supply may not exceed an absolute pressure of 10 bar (pressure gauge and safety value recommended for use in the supply line).



- If a humidity calibrator is filled with water and ready for operation, it must not be tilted by more than 20° during transportation. If this is not possible, HUMOR 20 must be drained completely --> see section "10.2 Empty water".
- Once HUMOR 20 has been switched off, it must also be disconnected from the compressed air (because of possible condensation in the lines as the heating is turned off).

5 OPERATING PRINCIPLE



Air or nitrogen under pressure p1 is fed into chamber 1 and humidified.

The developing saturation vapour pressure ews is a direct result of the temperature of the chamber respectively the water.

Next, the humidified air is expanded to pressure p and fed into chamber 2.

During expansion, the vapour pressure ews is reduced in the same ratio as the overall pressure of the air. Therefore, the water vapour pressure in chamber 2 is:

e = ews * p/p1

Thanks to the special design of HUMOR 20 with its high thermal conductivity, chamber 1 always has the same temperature as chamber 2.

Consequently, if the temperature is the same, the saturation vapour pressure ews of chamber 1 is identical to that of chamber 2. As a result of the expansion of the humidified air, chamber 2 contains the water vapour partial pressure e.

From the definition for relative humidity follows for chamber 2:

rh = e/ews = ews * (p/p1) / ews = p/p1



Hence, the relative humidity in chamber 2 is a direct result of the ratio of the pressures in chambers 1 and 2.

In addition, the relative humidity generated in HUMOR 20 is practically independent of the ambient temperature and only dependent on the pressures p and p1. The only precondition is that the temperature of chambers 1 and 2 and the water in chamber 1 is the same.

The relative humidity in chamber 2 can be varied by adjusting the inlet pressure p1. During operation, the pressures in chambers 1 and 2 are measured and the actual relative humidity is calculated with the above equation and shown in the display of the calibrator.

Schematic diagram of a two-pressure reactor

6 OPERATING COMPONENTS



6.2 Automatic calibration module (optional)



- Lights up: Setpoint reached

7 GENERAL USER INSTRUCTIONS

7.1 Setup

Operating range: 10...40°C / 10...80% rH.

Do not perform measurements in direct sunlight or while exposed to other external sources of heat.



Do not operate HUMOR 20 in potentially-explosive areas or expose it to strong mechanical vibrations.

If HUMOR 20 is transported when it is ready for operation (filled with distilled water), do not tilt the housing by more than 20°.

7.2 Starting up HUMOR 20



HUMOR 20 must acclimatise at least 6 hours on-site at the calibration location.

Apply voltage supply. Plug the power supply cable into the device and a grounded power outlet.

Turn the humidity controller to the left (anti-clockwise) as far as it will go.

Activate the main switch.





Open the water tank. Ignore the warm-up time. Use the Allen key supplied to open the screw plug.



Before opening the water tank, make sure that the humidity calibrator is no longer under pressure. Turn the humidity controller to the left (anti-clockwise) as far as it will go and wait until "RH > 90%" is shown in the display of HUMOR 20.



Fill HUMOR 20 with distilled water.

Fill the humidity calibrator with max. 1,300 ml distilled (deionised) water. If the maximum level is exceeded, the warning WATERLEVEL HIGH is shown in the display. If this happens, drain water until the warning disappears (see section "10.2 Empty water").

During the filling process, make sure that no water enters the $\sqrt{}$ measuring chamber.





Close the water tank. Use the Allen key supplied to tighten the screw plug.

Wait until the warm-up phase is completed. The warm-up phase will take 20 minutes (display: WARM UP TIME).



Attach the oil separator / filter set to the side of HUMOR 20, on the bracket, and establish a connection to the input "Pressure in".





Connect the pressurised (min. 8 bar) compressed air line to the filter set. A pressure less than 8 bar can cause leakage at the filter set. ($p \le 10$ bar - see safety instructions)

HUMOR 20 is ready for operation.





7.3 Starting up HUMOR 20 with automatic calibration module

Setting up HUMOR 20 with the automatic calibration module.



HUMOR 20 must acclimatise at least 6 hours on-site at the calibration location.



Establish a serial connection between HUMOR 20 and the automatic calibration module. Connect "RS232-Humor" on the automatic calibration module with "RS232" on HUMOR 20.

(Max. cable length allowed is 3m. The length of the supplied cable is 1.8m)



Connect the power cable to a grounded power outlet, but do not switch on the devices yet, using the main switch!



Establish a serial connection between the automatic calibration module and the PC/notebook.



First switch on HUMOR 20 using the main switch and then the automatic calibration module.



Open the water tank. Ignore the warm-up time. Use the Allen key supplied to open the screw plug.



Before opening the water tank, make sure that the humidity calibrator is no longer under pressure. Turn the humidity controller to the left (anti-clockwise) as far as it will go and wait until "RH > 90%" is shown in the display of HUMOR 20.



Fill HUMOR 20 with distilled water.

Fill the humidity calibrator with max. 1,300 ml distilled (deionised) water. If the maximum level is exceeded, the warning WATERLEVEL HIGH is shown in the display. If this happens, drain water until the warning disappears (see section "10.2 Empty water").

During the filling process, make sure that no water enters the measuring chamber.



Close the water tank. Use the Allen key supplied to tighten the screw plug.

Wait until the warm-up phase is completed. The warm-up phase will take 20 minutes (display: WARM UP TIME).

Establish a compressed-air connection between HUMOR 20 and the automatic calibration module.





Max. allowed hose length is 1m.

Attach the oil separator to the side of the automatic calibration module, on the bracket, and establish a connection to the input "Pressure in".



Unit

max. 12 TIF TME

10





Connect the pressure supply (oil-free compressed air or N2). A pressure less than 8 bar can cause leakage at the filter set. ($p \le 10$ bar - see safety instructions)



Turn the humidity controller to the right (clockwise) as far as it will go.

HUMOR 20 with the automatic calibration module is ready for operation.



7.4 Verifying the 100 %RH Point

To obtain the highest accuracy of the humidity measurement it is recommended to verify the 100 %RH point every 4 weeks during continues operation or each time before putting the Humor 20 into operation.

The verification has to be executed as follows:

- Turn the humidity controller counterclockwise all the way
- Disconnect the air pressure supply to the Humor



- Open the water inlet
- Open the measuring chamber (one opening is sufficient, see picture)
- Read the display after approx. 5 minutes:

Display reading	Final conclusion on performance	Required action
99.2% to 100.8%	HUMOR within specifications	A high accurate measurement can be realized
97.0% to 99.2% and 100.8% to 103.0%	HUMOR outside specifications	Adjustment is necessary to obtain the highest accuracy (see chapter "9.3.2. Calibration").
< 97.0% and >103.0%	HUMOR outside specifications	Adjustment is not possible. There is a problem with the humidity measure- ment / indication and the HUMOR should be returned to E+E Elektronik for calibration / repair.



8 CALIBRATION AND ADJUSTMENT PROCEDURE

The special design of the measuring chamber allows the calibration and adjustment of transmitters of varying sizes. These include cylindrical sensor probes with a diameter of 8-25.5 mm (0.3-1") (hand-held instruments, duct-mounted versions, ...) and room transmitters, data loggers, etc. with maximum dimensions of 100 x 85 x 40 mm (3.9x3.3x1.6") or 95 x 95 x 40 mm (3.7x3.7x1.6").



8.1 Cubical transmitters (room design) with HUMOR 20

HUMOR 20 can also be used to calibrate and adjust room devices using the Plexiglas cover for the measuring chamber provided in the scope of supply. Due to external thermal interference, additional measuring errors may occur depending on the adjusted humidity and the position of the test unit in the measuring chamber.

- 1. Place the test unit in the measuring chamber.
- 2. Lay the O-ring for the Plexiglas cover in the groove provided in the measuring chamber.
- 3. Feed the connection cable through the PG screw connection of the Plexiglas cover.
- 4. Fit the cover and tighten both knurled nuts.
- 5. Connect the test unit to the supply connections of HUMOR 20.
- 6. Connect the output signal of the test unit to the internal measuring inputs of HUMOR 20 (Unit1 RH, Unit2 RH)
- 7. Select the measuring range in accordance with the output signal of the test unit. The temperature of the measuring chamber can be displayed by selecting "Temp." on the measuring range switch.
- 8. For information on the standard deviations and stabilisation times of the test unit, refer to the manufacturer's documentation (however, a minimum of 20 mins is recommended).
- 9. Use the controller to select the setpoint of the humidity.
- 10. Compare the values shown in the display with the output signal of the transmitter.



8.2 Transmitter with cylindrical sensor probe with HUMOR 20

Because of the operating principle, HUMOR 20 has a slightly higher temperature than ambient. During the measurement process, make sure that the probe temperature can adapt to the temperature of the measuring chamber.

To ensure accurate measurements, the cover feedthrough must match the probe diameter as closely as possible. To ensure that this is the case, various cover designs are available (see the accessories appendix).

- Fit a suitable measuring chamber cover (note the position and diameter of the feedthrough) and tighten both knurled nuts.
 If inserted, remove the O-ring for the Plexiglas cover.
- 2. Insert the test unit(s) through the feedthrough(s) in the measuring chamber and tighten the screw connection(s).



If using the modules EE07 and EE08 (with cables) please note that only the filter caps get into the measuring chamber of the HUMOR to avoid falsification of the calibration through self heating effects (see picture on the left).



3.

Seal the openings of the feedthroughs not in use with the supplied plugs. Connect the test unit(s) to the supply connections of HUMOR 20 (24V DC).

Connect the test unit(s) to the supply connections of HUMOR 20 (24V DC).
 Make sure that the total power consumption of all transmitters is not more than 200 mA. In case the transmitters exceed this maximum, an external power supply has to be provided.

- 5. Connect the output signal of the test unit(s) to the internal measuring inputs of HUMOR 20 (Unit1 RH, Unit2 RH).
- 6. Select the measuring ranges in accordance with the output signal of the test units. The temperature of the measuring chamber can be displayed by selecting "Temp." on the measuring range switch.
- 7. Use the humidity controller to select the setpoint of the humidity.
- 8. For information on the standard deviations and stabilisation times of the test unit, refer to the manufacturer's documentation (however, a minimum of 20 mins is recommended).
- 9. Compare the values shown in the display with the output signal of the transmitter.

8.3 Transmitter EE33 Model J with HUMOR 20

To be able to calibrate the transmitter of the series EE33-MFTJ, with the dual probes (Td-probe and T–probe), a separate available adapter is needed (see chapter 13 'accessories' – adapter for EE33 – model J, part number HA020401) to achieve the highest possible calibration result. The following steps describe how the series EE33-MFTJ should be calibrated correctly.

- 1. Plug both air vents of the cover of the measurement chamber with the plugs supplied with the adapter (see left picture).
- 2. Insert the Td-probe (Ø12mm) in the measuring chamber through one of the feed-throughs of the cover and tighten the nut.
- 3. Insert and tighten the T-probe (Ø6mm) in the adapter and insert in the measuring chamber through one of the feed-throughs of the cover and tighten the nut.
- 4. In case that feed-throughs are not in use, close them with the blind plugs delivered with the cover.
 - Transmitters delivered after June 2009 have the possibility to heat the tube of the probe continuously to avoid condensation. This function must be disabled prior to calibration, by detaching the cover of the transmitter and removing the "heat"-jumper in the left top corner of the PCB (see left picture).
- 5. Connect the test unit to the supply connections of HUMOR 20.
- 6. Connect the output signal of the test unit(s) to the internal measuring inputs of HUMOR 20 (Unit1 RH, Unit2 RH).
- Select the measuring ranges in accordance with the output signal of the test units. The temperature of the measuring chamber can be displayed by selecting "Temp." on the measuring range switch.
- 8. Use the humidity controller to select the setpoint of the humidity.
- 9. For information on the standard deviations and stabilisation times of the test unit, refer to the manufacturer's documentation (however, a minimum of 20 mins is recommended).
- 10. Compare the values shown in the display with the output signal of the transmitter.



After calibration, make sure that the plugs in the air vents in the cover of the measuring chamber are removed.





8.4 Analogue Output HUMOR 20



On the back panel of the HUMOR 20 sits a 4-pole connector with the label "analog out".

Here are the conditions of the measuring chamber (RH, T) reproduced in the form of an analog signal.

Plug Connection:

Contact-Nr	Signal	Scaling
1	GND	
2	not connected	
3	RH_out	0-10V = 0-100% RH
4	T_out	0-10V = 0-50°C

8.5 Calibrations with the automatic calibration module

See section "9.4 Measurements".

8.6 Power failure during the calibration procedure

HUMOR 20

In the event of longer power failures (> 5min.), unlock (pull out) the controller's rotary knob and turn it anticlockwise as far as it will go. Disconnect the media supply. Once the power returns and the warm up phase has been completed, the calibration process can be resumed.

HUMOR 20 with the automatic calibration module

In the event of a power failure, an error message is displayed (see screenshot) and the calibration must be restarted.

LC Error		L
	Humor reports critical error condition!	
1[🔍	[2008-09-09 12:39:31] 0x43: Auto-Humor: Automatic mode interrupted (maybe power supply fault?)	Γ
2		
	ОК	
10000	OU:OU PIL DEL	1

8.7 Ending the calibration or adjustment procedure



If longer idle periods are expected, it is recommended to empty the distilled (deionised) water tank completely.

For more information, see section "10.2 Empty water tank".

Remove the supply pressure (compressed air) and turn off the main switch (if applicable, disconnect the grounding plug).

9 HUMOR 20 SOFTWARE

This software was developed by E+E Elektronik[®] in order to adapt the humidity calibrator HUMOR 20 to customer requirements, to log measured values, and to register the data in an adjustable measurement protocol.

9.1 Installing the software

- 1. Insert the CD-ROM supplied into your PC drive.
- 2. Close all other active programs.
- 3. Double-click on the file "Setup.exe".
- 4. Follow the instructions in the context menu.

Once HUMOR 20 is connected to the PC via the serial interface and the software is started, the alongside input windows appear.

Procedure:

- 2.

Language

German English

Please choose language:

Remember for next time

Select COM port

Select COM port

Remember for next time

ОK

X

4

-

×

Cancel

OK

Abort

- 1. Select the language.
 - Select the COM Port. Changes can be made at any time in the menu under "Operation" "Select COM Port".

3. Start screen:

Operation Calibratio	are ¥2.02.000 n Pressure compensation He	Þ		<u>-0×</u>	Menu bar
Configuration Meas	M Loonst urement Fixed value RH	! Error			Buttons to switch the control panels for the various opera-
Humor serial no.	093903000003		(n/a)	K	ting modes
Humor electronic	093902000001				
AutoHum, serial no.	09050300014176		AUTOHUM (V01.01)	Read	Control panel
AutoHum, electronic	084203000003				
Active calibration	Factory calibration	Temperature unit Celsius			
Log					
2009-10-07 09:53:	51: AUTOHUM (V01.01) 090503	00014176 [084203000003] Time=	π.		

On starting the software, the configuration modes starts automatically and the serial numbers and status of HUMOR 20 and the automatic calibration module are loaded.

9.2 Configuration mode control panel



Status of the calibration mode

Status of the temperature unit °C or °F

9.3 Menu bar

9.3.1 Operation

The pull-down menu "Operation" includes all the functions required to configure the humidity calibrator in accordance with customer requirements and to exit the program.

Aborts the warm up phase (20 mins).

The warm up phase is essential in order to achieve very accurate measuring results.

Abort warm up time:

Humor	20 Software V2.02	2.000
Operation	Calibration Pressu	ure compensatio
Abort w	arm up time	const
Toggle o Toggle t	xed value RH	
Design p	protocol	
Print protocol		001
Export r	neasurement data	14176

Toggle calibration mode:

Humor:	20 Software	e ¥2.02.000	
Operation	Calibration	Pressure compensatio	
Abort w	arm up time	const	
Toggle c	alibration mo	de ved value PH	
Toggle t	Toggle temperature unit		
Design p	rotocol		
Print pro	itocol	001	
Export n	neasurement	data 14176	

The humidity calibrator has 2 calibration modes. Users can switch between factory calibration and customer calibration.

The current calibration mode is shown in the start menu of the software and in the display of the humidity calibrator.



The temperature is set to SI or U.S. engineering units for the temperature to be displayed in degrees Fahrenheit or degrees Celsius.

<u>Toggle</u>	temperature	unit:

Humor	20 Software ¥2.02	2.000
Operation	Calibration Press	ure compensatio
Abort w	arm up time	const
Toggle c	Toggle calibration mode	
Toggle temperature unit		
Design p	rotocol	
Print pro	tocol	001
Export n	neasurement data	14176

Design protocol:

Humor	20 Software ¥2.02	2.000
Operation	Calibration Press	ure compensatio
Abort wa	arm up time	const
Toggle c Toggle ti	alibration mode emperature unit	xed value RH
Design p	rotocol	
Print pro	tocol	001
Export m	neasurement data	14176
Select COM port		003
Exit	ompore	alibration

In addition, the HUMOR 20 software provides the option of automatically generating a measurement protocol.

A ready-made template is defined and on completion of the measurement filled out automatically with the calculated values. Immediately after the end of the measurement process, a protocol in a well-organised format can be generated at the touch of a button.





E+E Elektronik offers a ready-made standard template that opens automatically on selection of the function "Design protocol". This standard template can easily be altered to meet customer requirements.

To create a fully customer-specific layout for the measurement protocol, the help text for the protocol designer has to be read carefully because of the wide range of options and functions. Therefore, the following approach is recommended:



To minimize the effort to create the form / protocol, just change the text fields or logo of the standard template only.

To do so, choose "Save as" from the menu and save the standard protocol under a new file name of your choice.

To make sure that the standard template will no be changed, open the protocol designer again and choose the file just created and change it as desired.



To enter your own logo in the protocol, select the placeholder (arrow 1). Your logo can be integrated in the protocol template by clicking on the specified path in the menu "Properties-Data-Source-File Name" (arrow 2).

Changing text fields:



To change text in the measurement protocol, choose the required text field (arrow 1) and click on the icon in the menu "Properties - Data - Contents" (arrow 2).

You can change the text and format as desired in the pop-up window "Paragraph Properties" (arrow 3).

In this way, you can easily substitute the German text for text in the relevant language.

New protocol template:



If you would like to create a complete new protocol template, refer to the information in the protocol designer's help text.

If you have any questions, pleased contact the E+E Elektronik customer service team directly.

To simplify the design of your own measurement protocol, the list below provides an overview of the most important variables and fields as well as their content.

Variables: Fields: Contents can be incorporated directly into the form design. Contents of fields can in addition be incorporated in every row of a table dependent on the

number of measurement points (dynamic).





Print protocol:

Humor	20 Software	¥2.02.000
Operation	Calibration	Pressure compensatio
Abort w	arm up time	const
Toggle c Toggle t	alibration mode emperature un	e xed value RH
Design p	rotocol	
Print pro	tocol	001
Export n	neasurement d	ata 14176
Calaako	003	
Selection	OM port	alibration
Exit		



On completion of the measurement process, the measured values can be printed in a protocol.

Use the command "Open" to choose between two pre-installed protocols. If you have created your own protocol, this can also be selected here.

Export measurement data:

🚰 Humor:	20 Software V2.02	2.000						
Operation	Calibration Press	ure compensatio						
Abort w	Const							
Toggle o Toggle t	Toggle calibration mode Toggle temperature unit							
Design p	Design protocol							
Print pro	itocol	001						
Export n	neasurement data	14176						
Folget C	OM port	003						
Select C	Ompore	alibration						
Exit								

You can export the measurement data to Microsoft Excel®.

Select COM port:

Humor	20 Software ¥2.02	2.000
Operation	Calibration Press	ure compensation
Abort wa	const	
Toggle c Toggle t	alibration mode emperature unit	xed value RH
Design p Print pro	rotocol itocol	001
Export n	neasurement data	14176
Select C	OM port	003 alibration
Exit		

You can use this function to change the COM port.

Exit:

The program is closed.

9.3.2 Adjustment / Calibration

6 point Humidity calibration:

Operation	Calibratio	n Pressure compensation					
Sh	6 pts. Humidity calibration						
Configurati Humor :	Temperature calibration Monitoring sensor calibration Analog measurement input calibrati						
Humor e	Reset	Reset to Factory settings					
AutoHum. s	erial no.	09050300014176 084203000003 Customer calibration					
AutoHum. el	lectronic						
Active ca	libration						

Only possible in the "CUSTOMER-Calibration" mode (refer to chapter 9.3.1). During the humidity adjustment, HUMOR 20 is equalised at 6 points with a highly-accurate external reference (certified chilled mirror dew point meter).

- The following additional equipment is required:
- Calibration cover (available on request from E+E Elektronik)
- Certified chilled mirror dew point meter as a reference
- Flow meter

Humidity adjustment procedure:



- 1. Fit the calibration cover (available on request from E+E Elektronik) and connect with the chilled mirror dew point meter.
 - The total length of the pipe should be no longer than 60 cm in total and must be thermally insulated along its entire length.



2. In order to acclimatise the measurement setup to the ambient temperature the Humor 20 should run an additonal two hours after warmup.



3. Connect the flow meter to the gas outlet of the chilled mirror dew point meter.

Set HUMOR 20 to a humidity value of 50% RH and set the correct gas flow for the chilled mirror dew point meter (refer to the manual of the dew point meter).

Example: Chilled mirror dew point meter MBW DP30 is 1 l/min

4. Remove the flow meter after setting the flow.

ib	ration table	Humor %arH	Deference %rH	Dev %rH	
	15	Trainer 70111	NETERCE ANTI	Derr /orri	
1	35				
	55				
	75				
1	85				
		mor:	mperature)		





Now you can start the adjustment process:

5. Set the adjustment point (e.g. 10% RH).



The stabilisation time between the adjustment points should be at least 20 mins.

- 6. Enter the humidity value on the HUMOR 20 display and the reference value of the chilled mirror dew point meter into the corresponding software fields and confirm your entries by pressing "Store".
- 7. Repeat steps 5 and 6 for measurement points 2 5.
- 8. The 6th adjustment point is set at 100% RH. Therefore disconnect HUMOR 20 from the compressed air supply.

9. Open the water tank.

Enter the humidity value in the HUMOR 20 display and the reference value of the chilled mirror dew point meter into the corresponding software fields and confirm your entries by pressing "Store".

 Once adjustment is complete, the calculated deviation is stored as a reference in the microprocessor. The adjustment procedure is complete.

Temperature calibration:

Operation	Calibratio	on Pressure compensatio					
Sha	6 pts.	6 pts. Humidity calibration					
Configurati	Temperature calibration						
coningaradi	Monitoring sensor calibration						
Humor :	Analog measurement input calibr Reset to Factory settings						
Humor e							
AutoHum. s	erial no.	09050300014176					
AutoHum, e	lectronic	084203000003					
Active ca	libration	Customer calibration					

emperature calibration	I									
Temperature										
Reference temperature: 23.11 °C										
-Info										
Enter reference temperature value (measured in Humor chamber)										
23°C +/- 10°C										
Store Abort										

Monitoring sensor calibration:

Humor2	0 Softwa	re ¥2.02.000					
Operation	Calibratio	ion Pressure compensati					
Sh	6 pts. Humidity calibration						
n 👒	Temperature calibration						
Coningaladi	Monitoring sensor calibration						
Humor :	Analog	measurement input calibr					
Humor e	Reset to Factory settings						
AutoHum. s	erial no.	09050300014176					
AutoHum. e	lectronic	084203000003					
Active ca	alibration	Customer calibration					
Log							

lonitoring sensor calibration	2
Options	
Vse Auto-Humor	Start
Step 1	
Target: 30% RH (+/- 5% RH)	Set 1
	00:00 left
Step 2	
Target: 75% RH (+/- 5% RH)	Set 2
	00:00 left

Analog Measurement Input Calibration:

Operation	Calibration Pressure compensation								
Sh	6 pts. Humidity calibration								
Configurati	Temperature calibration Monitoring sensor calibration								
Humor :	Analog	g m	easurement input calib						
Humor e	Reset	Reset to Factory settings							
AutoHum. s	erial no.	09050300014176							
AutoHum, electronic Active calibration			084203000003						
			Customer calibration						

Only possible in the "CUSTOMER calibration" mode. The temperature is equalised with a temperature standard.

A stabilisation time of 2h is recommended.

- 1. Insert an external temperature standard into the measuring chamber.
- Enter the reference value in the input field. Important: Temperature must be within the range 23°C ± 10°C.
- 3. With "Store" the adjusted temperature value is implemented.

Only possible in the "CUSTOMER calibration" mode. This function can be used to adjust 2 points of the humidity transmitter integrated in HUMOR 20 for monitoring purposes.

Procedure:

- 1. Acclimatise HUMOR 20 to the ambient conditions (temperature homogeneity).
- 2. HUMOR 20 should run for an additional 2 hours after the warm up phase.
- 3. Set the lower setpoint to 30% RH.
- 4. Once the stabilisation time has expired (30 mins), equalise the "Monitoring Sensor" to the reference value of HUMOR 20.
- 5. Set the upper setpoint to 70% RH.
- 6. Once the stabilisation time has expired (30 mins), equalise the "Monitoring Sensor" to the reference value of HUMOR 20.

With this function, the analog measurement inputs of the Humor20 (1-4) can be checked:

- 1. Select with Switch1 (see 6.1) either a current or a voltage range.
- 2. Select with Switch 2 (see 6.1) the measurement input to be tested.
- 3. Connect the external signal source with the selected Humor20 measurement input (1-4).
- 4. Set the analogue signal from the external source (0 10 V or 0 20 mA)
- 5. In the display the measured value will be indicated.

Reset to Factory settings:

Operation	eration Calibration Pressure compe							
Ya	6 pts.	Humidity calibration						
Configurati Humor :	Tempe Monito Analog	perature calibration toring sensor calibration og measurement input calib et to Factory settings						
Humor e	Reset							
AutoHum. s	erial no.	09050300014176						
AutoHum. e	lectronic	084203000003						
A shires as	libration	Customer calibration						

Humor20 Software V2.02.000 Operation Calibration Pressure compensation

A

Configuration Measurement Fixed value RH

Active calibration Customer calibration

093903000003

093902000001

09050300014176 084203000003

X

Humor serial no.

Humor electronic AutoHum, serial no.

AutoHum. electronic

Pressure compensati

All of the adjustment's calibration data is reset to the factory calibration default values.

9.3.3 Pressure Compensation

This function is used to equalise the two pressure transmitters of HUMOR 20.



For accurate measurements, the equalisation should be performed every 4 weeks.



Mode of operation:

The offset of the absolute pressure transmitter in the saturation chamber P_1 (0-10 bar) is aligned to $P_2 = P_{Reference}$ in the measuring chamber.

$$RH = \frac{p_2}{p_1} \times 100\% = \frac{978,7 \text{ hPa}}{978,7 \text{ hPa}} \times 100\% = 100\%$$

Transmitters P_1 and P_2 are now aligned to the atmospheric pressure. Calibration (adjustment) has been performed at 100% RH.

9.4 Measurements

9.4.1 Start screen

Hur	nor20 Softv	vare ¥2.02.00	0									1
Operat	ion Calibrat	ion Pressure o	ompensatio	n Help								
Config	uration Mea	asurement Fixe	ed value RH	Error								
Test	units											
Test	unit count:	2 Apr	oly	Re	ad specim	ens		Store Co	nfig. L	.oad Config.		
	Output	Range/Prot	. Unit/Po	rt Test unit	Ser.No.	Туре	Make Cu	istomer	Cal.No.			"Test units" configuration field
1	Manual input Manual input											
1	nanaan mpac					1 1						
Meas	urement worl	kflow										
Meas	urement poir	its count: 3	App	bly	🔽 Set	measured	values aut	omatically		Start		
ΠL	og measured	values addition	ally in fixed	interval: 5	Secon	ls						
	Target RH	Target time [min]	Spec. dev. RH	Actual time [min]	Ref. Temp.	Ref. RH	Meas.va #1 RH	al Dev. #1 RH	Meas.v #2 RH	al Dev. #2 RH		"Measurements" configuration field
1												
2											-	
								00	:00 left	Set		
Info												
* Co	nfigure test i	unit count and p	roperties								-	
* De * Pr	fine points to	measure										Info field
Ready											1	

9.4.2 "Test unit" configuration field

Enter the number of test units to be measured in the "Test unit count" field and confirm your entry by pressing "Apply". You can now enter the configuration for each test unit.

Output:

Test Test	t units t unit count: 🏹	2	Appl	y	
	Output	Rang	je/Prot.	Unit/Port	Tes
1	Manual inț 💌				
2	Manual input Analogue (Hu				

Here you choose how the test unit's measured value should be entered:

<u>Manual input:</u> Once the stabilisation time has expired, the measuring program waits until the measured value is entered manually. Press "Set" to confirm your entry.

<u>Analogue (Humor20)</u>: Once the stabilisation time has expired, the measured value is adopted automatically by the measuring input of HUMOR 20.

Range/Prot.:

T T	'esl Tes	t units t unit count:	2		Appl	у		
[Output	Rang	je/Pr	ot.	Unit	/Port	Te
	1	alogue (Humor	<choo< td=""><td>ose></td><td>-</td><td><unit< td=""><td>: 1,2></td><td></td></unit<></td></choo<>	ose>	-	<unit< td=""><td>: 1,2></td><td></td></unit<>	: 1,2>	
	2	Manual input	<choo< td=""><td>se></td><td></td><td></td><td></td><td></td></choo<>	se>				
ן אן- א	1ea 1ea	isurement work asurement point	01 V 05 V 010 020 420	V mA mA			Apply	

[Only active with the "Analogue (Humor20)" output]

Here, you select what the output signal of the test unit is.

Unit/Port:

es	t unit count:	2 A	pply
	Output	Range/Pro	. Unit/Port
1	alogue (Humor	<choose></choose>	1
2	Manual input		



[Only active with the "Analogue (Humor20)" output]

Select the measuring input (Unit 1 - Unit 4) used to connect the test unit to HUMOR 20.

Note: the rotary knob of the HUMOR 20 has to be set at the correct measurement input as well, to indicate desired measurement value in the display.

Test unit / Ser.No / Type / Make / Customer / Cal.No:

i

es	it unit count: 📑	3 Appl	У			Read	specimer	ns		Store Config.	Load Config
D.	Output	Range/Prot.	Unit/Port	Test unit	Ser.No.	Туре	Make	Customer	Cal.No.		
1	alogue (Humor	010 V	1	EE08-PFT3D6T02	000977865	RH/T	E+E	Mustermann	K000978		
2	alogue (Humor	010 V	2	EE08-PFT3D6T02	000967865	RH/T	E+E	Mustermann	K001000		
3	alogue (Humor	010 V	3	EE08-PFT3D6T02	000988888	RH/T	E+E	Mustermann	K000002		

<u>Test unit:</u>	Enter the type designation of the test unit here. This field can be included in the protocol.
Ser.No:	Enter the serial number of the test unit here. This field can be included in the protocol.
Туре:	Enter the type of the test unit here. This field can be included in the protocol.
<u>Make:</u>	Enter the make of the test unit here. This field can be included in the protocol.
Customer:	Enter the name of the customer here. This field can be included in the protocol.
<u>Cal.No:</u>	Enter the calibration number (your internal number) for the job. This field can be included in the protocol.
	You can save the configuration for the test unit(s) by pressing the "Store Config." button. To load a stored configuration, choose "Load Config.".

9.4.3 "Measurements" configuration field

				1.4						
Measurement points count: 3 Apply						Set measured values automatically				
Γ	Log measured	values additiona	ally in fixed	interval: 5	Second	ls				
	Target RH	Target time [min]	Spec. dev. RH	Actual time [min]	Ref. Temp.	Ref. RH	Meas.val #1 RH	Dev. #1 RH	Meas.va #2 RH	
1	Target RH	Target time [min]	Spec. dev. RH	Actual time [min]	Ref. Temp.	Ref. RH	Meas.val #1 RH	Dev. #1 RH	Meas.va #2 RH	

Measurement points count:

Enter the number of measurement points and confirm your entry by pressing "Apply".

Set measured values automatically: Checkbox selected: The test unit's measured value at the measuring input of HUMOR 20 is set automatically once the stabilisation time has expired. Checkbox not selected: The program waits for the measured value to be entered manually once the stabilisation time has expired.

Log measured values additionally in fixed interval:

If you select this checkbox, the test unit's measured values will be logged by the measuring input of HUMOR 20.

The measured values are stored in the file "MeasLog.csv" in the program directory of the HUMOR 20 software.

	Mea Mea	surement wor surement poir Log measured	kriow hts count: 5 values additiona	Ap ally in fixed	ply inl	, terval: 60	Second	measured · is	values a
(Target RH	Target time [min]	Spec. dev. RH		ctual time [min]	Ref. Temp.	Ref. RH	Meas. #1 R
	1	10	00h 45min	3					
	2	15	00h 30min	3					
	3	20	00h 30min	3					
	4	30	00h 30min	3					
	5	50	00h 30min	3					

Now you can set the measurement points:

Target RH:

Enter the humidity value of the measurement point, e.g. 20 for 20% RH.

Target time [min]:

Spec. dev. RH:

Enter the permitted tolerance for the measurement point. You can only enter numerical values (e.g. 2 for ±2% RH).

Enter the required stabilisation time in minutes (e.g. 20 for 00h 20min or

Once all the measurement points have been fully configured, you can start the measurement by pressing the "Start" button.



80 for 01h 20min).

If using an automatic calibration module, turn the humidity controller to the right (clockwise) as far as it will go, refer to chapter 7.3.

The automatic calibration module now adjusts to the first measurement point.

	Target RH	Target time [min]	Spec. dev. RH	Actual time [min]	Ref. Temp.	Ref. RH	Meas. #1 R
1	10	00h 45min	3	00h 00min	23.24	9.63	
2	15	00h 30min	3				
3	20	00h 30min	3				
4	30	00h 30min	3				
5	50	00h 30min	3				

During this adjustment procedure, the orange LED "auto" on the automatic calibration module flashes. Once the setpoint has been reached, the LED lights up continuously.

If the measurement point is reached within a range of ±1% RH, the stabilisation time for the measurement point begins to run. Once the stabilisation time has expired, depending on whether the checkbox "Set measured values automatically" has been selected, either the system enters the value of the measuring input of HUMOR 20 or waits for a manual entry.

Once the measurement is completed, the automatic calibration module adjusts the humidity to 10% RH (orange "auto" LED goes out). The measured values are stored in the program directory

[.....\E+E Elektronik\HUMOR-20\MeasData]. The file name consist of the current date and time

e.g. 2008-08-25_12_10_05.hmf

Note: If the measurement is aborted, no measured values are stored!

Operation Ca	libration Press	ure compensation	Help	
She	In	Const		
ର୍ତ୍ତ 👒 Configuration	Measurement	Fixed value RH	Error	
		F	ixed humidity value	
		T	arget value:	
			60	-
			00	-
		1		
			Start	Stop
		-		

i

i

9.5 Fixed RH Value (only available when using an automatic calibration module)



The humidity control knob of the Humor20 has to be turned to the right (clockwise) all the way to the stop, see chapter 7.3

Start Button: as soon as the desired value is entered and the "Start-Button" is pressed, the desired humidity in the measurement chamber will be set by the Automatic Calibration Module (orange "auto" LED blinks or illuminates)

Stop-Button: activating the "Stop-Button" will end the control of the Automatic Calibration Module (orange "auto" LED not illuminated); in this way, a humidity level of 10 %RH will be set in the measuring chamber of the Humor20.

10 MAINTENANCE

The distilled (deionised) water should be changed every 8 weeks. If the unit is idle for longer periods, all the water should be removed.

rel. HUM. =100.0% WATERLEVEL LOW

10.1 Re-fill water (at error message Waterlevel low)

- 1. Turn the humidity controller all the way to the left and wait until the message "OUT OF SPEC" is displayed.
- 2. Remove the screw plug.
- 3. Fill with distilled (deionised) water (when the error message "Waterlevel low" is displayed, a max. of 1,000 ml can be added).
- 4. Replace the screw plug and tighten.
- 5. If the maximum fill level is exceeded, the error message "Waterlevel high" is displayed, and water must be removed until the message on the display disappears.
- 6. After filling, wait for a stabilisation time of around 20 mins (the higher the difference in temperature between the water and the humidity calibrator, the longer the stabilisation time ought to be).
- 7. HUMOR 20 is ready for operation.

rel. HUM. =100.0% WATERLEVEL HIGH



10.2 Drain water (at error message Water-Level high or long idle periods)

- 1. Turn the humidity controller all the way to the left and wait until the message rel.HUM high appears in the display.
- 2. If you are using the automatic calibration module, connect the compressed air supply directly to HUMOR 20.
- 3. Connect the water drain hose to the discharge nozzle.
- 4. Turn the humidity controller slowly to the right until water drains out.
 a) Until the "Waterlevel high" message disappears.
 b) Until the saturation chamber is completely empty. To make sure that the chamber is completely dry, flow air through the device for a short time.
- 5. To end the drainage process, turn the humidity controller to the left again as far as it will go.
- 6. Disconnect the compressed air and the water drain hose.
- 7. HUMOR 20 can now be turned off.

11 WARNINGS / ERROR MESSAGES IN THE DISPLAY

1st line: Displays moisture () or error () 2nd line: Status bar () and actual value of the test unit on HUMOR 20

rel. HUM. =100.0% WATERLEVEL LOW

rel. HUM. =100.0%

The humidity calibrator is equipped with an auto diagnostic system. It issues different operating or error messages depending on the operating status or error. You can remedy the cause of the messages as follows:

CAUSE

REMEDY



11.1 Humidity - display flashes

1. After a sudden change in the setpoint, the measuring chamber has not reached the desired value immediately. As soon as the difference between the relative humidity shown in the measuring chamber and the setpoint exceeds a defined range, the display starts to flash.

Wait for the stabilisation time to end (after a few minutes, the display should stop flashing automatically).

2. Water in the measuring chamber or internal lines.

This error is usually caused by transporting a HUMOR 20 device filled with water or connecting compressed air when the humidity controller has not been turned all the way to the left. Dry the measuring chamber with an absorbent cloth. Drain the water, and let compressed air or nitrogen flow through the device for a lengthy period. This is achieved by specifying a setpoint of 75% on the humidity controller. During the purging (drying), the display flashes and the warning WATERLEVEL LOW is shown. The drying process lasts around 48h and should monitored be bv а test unit. The drying process is complete as soon as the test unit shows a relative humidity of < 15%.

This process can be accelerated by using dry compressed air or dry nitrogen.



11.7 Humidity - display is incorrect

Incorrect display, e.g. because of an Che error in the electronics.

Check HUMOR 20. Turn the controller to the left as far as it will go and disconnect the compressed air. After a stabilisation time of 2h, the display should show 100 $\pm 2\%$ RH. If this is not the case, contact your E+E Elektronik sales partner. The response time of HUMOR 20 for a jump in humidity from 25 to 80% RH and from 80 to 25% RH is shown in the graph. A jump to a lower value requires approx. 1 minute, while a jump to a higher humidity value requires approx. 3 minutes.

The required stabilisation time is determined primarily by the test unit.

Considering the response times of instruments now available on the market (equipped with standard filters), stabilisation time of approx.20 minutes а measurement point can be expected.



CAUSE

Valve defect.



Check the flow.

1. Drain all the water completely and refill the humidity calibrator with exactly 1000 ml of distilled water.

2. Specify a humidity setpoint of exact-

ly 20% RH. 3. Turn the humidity controller all the way to the left and measure the time it takes for the value 80%RH to appear in the display.

- If the time measured is < 80sec, the flow is correct and within the working range.
- If the process takes much longer, contact your E+E Elektronik sales partner.



Ī

11.9 Electronic defect - replace electronics

Replacing the electronics:

- 1. Disconnect the humidity calibrator from the supply voltage.
- 2. Loosen the screws (see Fig. 1).
- 3. Loosen the recessed-head screws on the 19" rack (see Fig. 2).
- 4. Pull out the plug-in module (electronics) (see Fig. 3).
- 5. Insert the replacement electronics and close the housing.
- 6. Calibrate HUMOR 20.



The factory calibration is lost when the electronics are replaced!

If you have any questions, please contact your E+E Elektronik sales partner.

11.10 Leakage in filter set

You will hear if there is a leakage in the filter set (escaping air).

Disconnect the compressed air supply and check the pressure. Make sure the supply is at least 8 bar. Reconnect the pressure supply.

Fig. 1





12 TECHNICAL DATA

General

Function principle	two-pressure-read	ctor
Working range	1095% RH	
Accuracy of measurement ^{1) 2)}	1,00	
(Traceable to international	0,75 -	
standards, administrated by		
NIST, PTB, BEV)		
	표 0,25 - 안	
	° 0,00	
	≥ -0,25	
	⊃ _0.50	
	-0,00	
	-0,75 -	
	-1,00	
		relative humidity Uw [% RH]
Accuracy temperature measure-		
ment in measuring chamber ²⁾	typ. ±0.3°C (±0.54°	°F)
Power supply	90230V AC	
Work equipment	 compressed air, fi 	iltered and free of oil or nitrogen N_2 with max. 10bar (145psi)
	 distilled water 	
Stabilisation time HUMOR 20	< 3 min/measurin	g point
Stabilisation time specimen	typ. 20 min/meas	uring point
Integrated power supply	24V DC, max. 20	0mA
Number of measuring inputs	4 (switchable bet	ween 420mA / 020mA / 01V / 05V / 010V)
Typ. error for display inputs	Voltage measurin	g: < 5mV
	Current measurin	g: < 30μA
Display	Dot-matrix display	y with backlight
Gas flow	3 l/min	
	for RH $> 85\%$ the	gas flow is reduced to 1.5 l/min at 95% RH
Recommended interval for	4	
recalibration	1 year	0
Interface for PC connection	RS232 (COM por	
System requirements for	INS WINDOWS 200	U WITH SP 2 / WINDOWS XP /
software tools	Windows Vista	
Environmental conditions	temperature:	1040°C (50104°F)
· · · · · · · · · · · ·	humidity:	1080% RH
Applied harmonised standards	EN 61000-6-3	EN 60068-2-6
	EN 61000-6-2	EN 61010-1
	EN 61326-1	EN 60068-2-29
Dimensions	400 x 260 x 240 i	mm (15.7 x 10.2 x 9.4")
vveight	HUMOR 20: abou	ut 23kg (51 lbs)
	HUMOR 20 incl.	aluminium transport case: about 36.5kg (80.5 lbs)

Measuring Chamber

The construction of the measuring chamber allows the calibration and adjustment of cylindrical sensor probes with a diameter of 8-25.5mm (0.3-1") (hand-held instruments, duct-mounted versions, ...) as well as of cubic measuring units (room transmitters, data loggers, ...) with maximum dimensions of 100x85x40mm (3.9x3.3x1.6") or 95x95x40mm (3.9x3.9x1.6").

By using the Plexiglas cover (standard supply), it is possible to calibrate and adjust compact room devices (e.g., the EE10) with the HUMOR 20.

The overall accuracy of the calibration is influenced by the absence of the metal cover. The additional error depends on the position of the specimen in the chamber as well as on the relative humidity.

1) The extended inaccuracy of measurement results from the standard inaccuracy increased by a multiplying factor of K=2.

2) Valid for metal covers for the measuring chambers

13 ACCESSORIES

Compressor with oil separator

Technical Data:

Max. operation pressure	12bar (174psi)
Supply voltage	100, 120, 200 or 230V AC // 50 or 60Hz
Noise level	45dB(A)/Im
Dimensions (I x w x h)	380 x 380 x 480 mm (15 x 15 x 18,875 ")
Weight	26kg (57lbs)



Optional covers for the measuring chambers

Various covers for the measuring chamber accommodate probes of all diameters available on the market.

With these covers up to four probes can be calibrated simultaneously.

SUITABLE FOR	NUMBER OF FEEDTHROUGHS	ORDER CODE
probe Ø 8 - 12mm (0.3 - 0.5")	3	HA020204
probe Ø 12 - 16mm (0.5 - 0.6")	2	HA020201
probe Ø 16 - 20.5mm (0.6 - 0.8")	1	HA020202
probe Ø 20.5 - 25.5mm (0.8 - 1")	1	HA020203
probe Ø 12mm (0.47 - 0.51")	4	HA020205
probe Ø 12 - 16mm (0.5 - 0.6")	4	HA020207
HUMLOG 10	-	HA020206
adapter for EE32/33-J ¹⁾	1	HA020401

1) only useable in combination with HA020204 or HA020201

Calibration certificate

To meet the requirements of Quality Management Systems such as ISO9001 regarding calibration and certification of measurement and test instrumentation, the HUMOR 20 is available with an official OEKD accredited calibration certificate.



Automatic Calibration Module

For the fully automatic measurement of the characteristics of a transmitter.

Technical Data:

Weight	- weight of instrument: 9kg (20lbs) - instrument incl. aluminium transport case: 23kg (51lbs)
Dimensions	260x260x240mm (LxBxH); (10.2"x10.2"x9.4")
Supply	90230V
Interface to PC	RS232 (COM Port)
Compressed air supply	min. 9.8bar (142psi); max. 12bar (174bar) oil-free filtered compressed air, max. size of particle: 5µm
Protection class	IP40
Scope of supply	 automatic calibration module power supply cable IEC Europe (230V) power supply cable IEC Northamerica (110V) RS232 connection cable to Humor 20 compressed air connection cable to Humor 20



YOUR PARTNER IN SENSOR TECHNOLOGY

HEAD OFFICE:

E+E ELEKTRONIK Ges.m.b.H. Langwiesen 7 A-4209 Engerwitzdorf Austria Tel: +43 7235 605 0 Fax: +43 7235 605 8 info@epluse.com www.epluse.com

TECHNICAL OFFICES:

E+E CHINA / BEIJING Tel: +86 10 84992361 info@epluse.cn

www.epluse.cn

ELEKTRONIK®

E+E CHINA / SHANGHAI Tel: +86 21 61176129 info@epluse.cn www.e

www.epluse.cn

E+E GERMANY Tel: +49 6172 13881 0 info@epluse.de

www.epluse.de

E+E FRANCE Tel : +33 4 7472 35 82 info@epluse.fr

E+E ITALY Tel: +39 0331 177 31 02 info@epluse.it

www.epluse.it

www.epluse.fr

E+E KOREA Tel: +82 31 728 2223 info@epluse.co.kr

www.epluse.co.kr